


Fig. 7: Elimination of SiOH and HF Absorption Peaks in 100 PSI H2 & 100C.









Fig. 9: Attenuation of SiC4 Treated Fiber before Hydrogen Exposure.



Wavelength (nm)